



1. Dislodged/eroded drainage pipe behind Oak Summit Apartments (right bank)
Action/BMP: Repair stormwater pipe



2. Unknown drainage pipe from Oak Summit Apts, possible drainage from indoor pool.
Action/BMP: Follow-up with the apartment management.




3. Spread of knotweed along left bank
Action/BMP: Develop eradication program for knotweed



4. Vertical creek bank behind Oak Summit Apts., scouring of bank and undercutting
Action/BMP: Develop a plan for biotechnical streambank restoration



5. Broken concrete bulkhead
Action/BMP: Have the township engineer assess the problem and develop solution.



Visual Streambank Assessment

TOOKANY CREEK WATERSHED MANAGEMENT PLAN

Township of Cheltenham


Holy Sepulchre Cemetery to Abington Township Border

Assessed by the Tookany Creek Watershed Steering Committee Members

● Visual Assessment Point



500 0 500 Feet



Prepared By:



85 Old Dublin Pike
 Doylestown, Pa 18901
 215-345-7020
 www.heritageconservancy.org

NAM Planning
 & Design LLC



Funded in part by a grant from the Pennsylvania Department of Conservation and Natural Resources (DCNR) & the Pennsylvania Department of Environmental Protection (PA DEP).



6. Broken/breached concrete collar of sanitary sewer
Action/BMP: Have the township engineer assess the problem and develop solution



7. Erosion of streambank
Action/BMP: Develop a plan for biotechnical streambank restoration



8. Discolored water & storm drain from General Patterson Drive
Action/BMP: Follow up on the source of the discharge.



9. Stream bank erosion
Action/BMP: Develop a plan for biotechnical streambank restoration



10. Discolored water in deep pool behind Kaname Gardens adjacent to Waverly Road
Action/BMP: Follow up with the nursery owner